





1. Table of Contents (This Page)
Created on Tue Sep 30 14:46:46 2014


- 2. component
- 3. solder
- 4. outline
- 5. plated-drill
- 6. componentmask
- 7. soldermask
- 8. topsilk
- 9. bottomsilk
- 10. topassembly
- 11. bottomassembly
- 12. fab



























There are 9 different drill sizes used in this layout, 54 holes total

Symbol	Diam. (Inch)	Count	Plated?
γ	0.020	2	YES
+	0.035	16	YES
x	0.038	4	YES
•	0.043	2	YES
□	0.048	2	YES
▽	0.051	14	YES
#	0.073	8	YES
⌘	0.095	4	YES
◎	0.128	2	YES

Title: (unknown) - Fabrication Drawing

Author: Nathan D. Holmes

Date: Tue 30 Sep 2014 00:46:46 PM GMT UTC



Board outline is the centerline of this path