





1. Table of Contents (This Page)
Created on Wed Aug 19 21:13:34 2020


2. component
3. solder
4. outline
5. plated-drill
6. componentmask
7. soldermask
8. topsilk
9. bottomsilk
10. toppaste
11. topassembly
12. bottomassembly
13. fab






























There are 7 different drill sizes used in this layout, 59 holes total

Symbol	Diam. (Inch)	Count	Plated?
γ	0.020	4	YES
+	0.030	28	YES
x	0.038	7	YES
°	0.043	2	YES
□	0.048	2	YES
∅	0.073	8	YES
⊕	0.128	8	YES

Title: (unknown) - Fabrication Drawing
Author: Michael Petersen
Date: Thu 20 Aug 2020 08:13:34 AM GMT UTC



Board outline is the centerline of this path