





1. Table of Contents (This Page)
Created on Mon Apr 17 13:18:47 2017


- 2. component
- 3. solder
- 4. outline
- 5. plated-drill
- 6. componentmask
- 7. soldermask
- 8. topsilk
- 9. bottomsilk
- 10. toppaste
- 11. topassembly
- 12. bottomassembly
- 13. fab






























There are 7 different drill sizes used in this layout, 101 holes total

Symbol	Diam. (Inch)	Count	Plated?
Y	0.020	38	YES
+	0.030	12	YES
x	0.038	30	YES
o	0.045	3	YES
□	0.048	10	YES
⌘	0.128	4	YES
⊕	0.129	4	YES

Title: (unknown) - Fabrication Drawing

Author: Nathan D. Holmes

Date: Mon 17 Apr 2017 07:18:47 PM GMT UTC



Board outline is the centerline of this path