





1. Table of Contents (This Page)  
Created on Mon Nov 2 11:26:00 2015


- 2. component
- 3. solder
- 4. outline
- 5. plated-drill
- 6. componentmask
- 7. soldermask
- 8. topsilk
- 9. bottomsilk
- 10. toppaste
- 11. bottompaste
- 12. topassembly
- 13. bottomassembly
- 14. fab

















bottommask (mirrored), scale = 1:1.000  
mrb-ant.pcb















C21X  
.. .  
C20X  
-  
C19X


C18X  
.. .  
C17X  
-  
C16X











bottomassembly (mirrored), scale = 1:1.000  
mrb-ant.pcb


There are 11 different drill sizes used in this layout, 344 holes total

Symbol	Diam. (Inch)	Count	Plated?
Y	0.020	236	YES
+	0.035	16	YES
x	0.038	52	YES
•	0.040	4	YES
□	0.045	9	YES
▽	0.048	14	YES
⊕	0.108	4	YES
⊗	0.110	2	YES
⊙	0.125	1	YES
⊠	0.128	2	YES
⊞	0.129	4	YES

Title: (unknown) - Fabrication Drawing

Author: Nathan D. Holmes

Date: Mon 02 Nov 2015 06:26:00 PM GMT UTC



Board outline is the centerline of this path