





1. Table of Contents (This Page)
Created on Sat Sep 17 15:31:18 2016


2. component
3. solder
4. outline
5. plated-drill
6. unplated-drill
7. componentmask
8. soldermask
9. topsilk
10. bottomsilk
11. toppaste
12. topassembly
13. bottomassembly
14. fab

































There are 7 different drill sizes used in this layout, 137 holes total

Symbol	Diam. (Inch)	Count	Plated?
Y	0.020	99	YES
+	0.030	16	YES
x	0.038	2	YES
o	0.039	3	NO
□	0.039	3	YES
⌘	0.048	6	YES
#	0.128	4	YES
⌘	0.129	4	YES

Title: (unknown) - Fabrication Drawing
Author: Nathan D. Holmes
Date: Sat 17 Sep 2016 09:31:18 PM GMT UTC



Board outline is the centerline of this path