




CONNECTOR TO MOTHERBOARD




PRESSURE SENSOR



HUMIDITY SENSOR



NOTE: SEE PG#3 OF MICS6814 DATASHEET. R1, R2, AND R3 RECALCUATED FOR 3.3V SUPPLY



VOLTAGE DIVIDERS FOR MEASURING GAS SENSOR RESISTANCE

GAS SENSOR