



AUTO POINT COLLISION REPAIRS & CAR PAINT

FINAL INVOICE

We provide High quality work and service at low price.

5801 Belair Road, Baltimore, MD 21206

Phone: (410) 488-4040

Workfile ID:

c9b42a0a

PartsShare:

8j3t3F

Preliminary Estimate

Customer: Buck, Carroll

Job Number:

Written By: S. Matthew
Adjuster: WILLIG, JONATHON

Insured: Buck, Carroll

Policy #:

Claim #: MD-805128-1

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact:

Owner:

Buck, Carroll

(202) 276-0123 Cell

Inspection Location:

AUTO POINT COLLISION REPAIRS & CAR PAINT

5801 Belair Road

Baltimore, MD 21206

Repair Facility

(410) 488-4040 Business

Insurance Company:

MGA INSURANCE COMPANY, INC.

VEHICLE

2021 GMC Terrain SLE FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection white

VIN: 3GKALMEV3ML317940

Interior Color:

Mileage In:

Vehicle Out:

License:

Exterior Color: white

Mileage Out:

State: MD

Production Date:

Condition:

Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Brakes

Power Windows

Power Locks

Power Mirrors

Heated Mirrors

DECOR

Dual Mirrors

Privacy Glass

CONVENIENCE

Air Conditioning

Cruise Control

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Backup Camera

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control

Stability Control

Front Side Impact Air Bags

Head/Curtain Air Bags

Communications System

Hands Free Device

Xenon or L.E.D. Headlamps

Lane Departure Warning

SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

Preliminary Estimate

Customer: Buck, Carroll

Job Number:

2021 GMC Terrain SLE FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection white

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER & GRILLE					
2		O/H bumper assy		0	0.00	3.8	0.0
3	**	Repl RECOND Bumper cover w/o park sensors	84418527	1	410.67	Incl.	3.0
4		Add for Clear Coat		0	0.00	0.0	1.2
5	**	Repl A/M CAPA Lower cover black, w/o fog lamps w/o oil heater	23394893	1	357.00	Incl.	0.0
6		Repl Energy absorber	23196301	1	197.05	Incl.	0.0
7	**	Repl A/M Guard	84766445	1	21.54	0.1	0.0
8	*	Rpr Upper support Note: adjust and touch up		0	0.00	<u>1.0</u>	<u>0.5</u>
9		Repl Front brace	84167659	1	28.92	0.2	0.0
10	*	Repl Grille assy SL, SLE +30% Note: recycled cox 4102886676 475.00	84236083	1	<u>615.71</u>	Incl.	0.0
11	*	Repl LKQ Grille assy SL, SLE	84236083	1	<u>0.00</u>	<u>Incl.</u>	0.0
12	#	Rpr lower grill texture repair		0	0.00	0.5	0.0
13		R&I Underbody shield 1.5 liter		0	0.00	Incl.	0.0
14	**	Repl A/M License bracket	23462463	1	23.00	0.2	0.0
15		FRONT LAMPS					
16		Repl Aim fog lamps		1	0.00	0.3	0.0
17		COOLING					
18	**	Repl A/M KEYSIQ Radiator	87830396	1	176.47 m	4.6 M	0.0
19	**	Repl A/M CAPA Shutter upper	84766744	1	208.20 m	Incl.	0.0
20	**	Repl A/M CAPA Shutter lower	84614525	1	106.00 m	Incl.	0.0
21		Repl Upper baffle	84618991	1	83.90	Incl.	0.0
22		R&I Lower baffle		0	0.00	Incl.	0.0
23	#	Repl antifreeze		2	50.00	0.0	0.0
24	*	Repl LKQ Fan assy +30%	84847896	1	375.70 m	<u>0.5</u> M	0.0
25	**	Repl A/M KEYSIQ Intercooler	85163204	1	195.45 m	Incl. M	0.0
26		HOOD					
27	*	Rpr Hood Note: see picture		0	0.00	<u>1.0</u>	3.0
28		Add for Clear Coat		0	0.00	0.0	1.2
29		R&I Insulator 1.5, 2.0 liter		0	0.00	0.3	0.0
30	*	Rpr Latch Note: ADJUST		0	0.00	<u>0.5</u>	0.0
31		R&I Latch		0	0.00	0.3	0.0
32		R&I Front w'strip		0	0.00	0.2	0.0
33		FENDER					
34	*	Rpr LT Fender		0	0.00	<u>1.0</u>	1.8
35		Overlap Major Adj. Panel		0	0.00	0.0	-0.4
36		Add for Clear Coat		0	0.00	0.0	0.3

Preliminary Estimate

Customer: Buck, Carroll

Job Number:

2021 GMC Terrain SLE FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection white

37		R&I	LT Fender liner	0	0.00	0.4	0.0
38		R&I	LT Fender liner	0	0.00	0.4	0.0
39	#	Blnd	L/S W/S PILLAR	0	0.00	0.0	0.5
40	WINDSHIELD						
41	*	Rpr	Windshield GM w/o Pre-crash Note: ROPE	0	0.00	0.5	0.0
42	#	Refn	FEATHER PRIME AND BLOCK	0	0.00	0.0	0.5
43	#	Subl	Hazardous waste removal	1	10.00 T	0.0	0.0
44	#	Repl	Cover Car	1	10.00 T	0.0	0.0
45	#	Repl	Flex additive	1	15.00 T	0.0	0.0
46	#	Repl	Corrosion protection primer	1	8.00 T	0.0	0.0
47	#		Cover interior	1	5.00 T	0.2	0.0
48	#		Mask jams/openings	1	5.00 T	0.2	0.0
49	#		PRE SCAN	1	0.00	0.5 M	0.0
50	#		POST SCAN	1	0.00	0.5 M	0.0
51	#	Rpr	D AND R BATTERY	0	0.00	0.3 M	0.0
SUBTOTALS				2,902.61		17.5	11.6

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				2,849.61
Body Labor	11.1 hrs	@	\$ 52.00 /hr	577.20
Paint Labor	11.6 hrs	@	\$ 52.00 /hr	603.20
Mechanical Labor	6.4 hrs	@	\$ 145.00 /hr	928.00
Paint Supplies	11.6 hrs	@	\$ 38.00 /hr	440.80
Body Supplies	12.3 hrs	@	\$ 3.00 /hr	36.90
Miscellaneous				53.00
Subtotal				5,488.71
Sales Tax	\$ 3,380.31	@	6.0000 %	202.82
Grand Total				5,691.53
Deductible				0.00
CUSTOMER PAY				0.00
INSURANCE PAY				5,691.53

MyPriceLink Estimate ID / Quote ID:

1298028217986195456 / 142217052

Preliminary Estimate

Customer: Buck, Carroll

Job Number:

2021 GMC Terrain SLE FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection white

By Signing I agree that Auto Point has my permission to diagnose and or repair the above mentioned vehicle. I agree that the final invoice amount may vary slightly from any estimated price that I was given by no more than 10 percent. Furthermore, I agree to hold autopoint harmless for any damages, or loss of items in or out of the vehicle. I agree to pay the agreed upon amount for repairs to the vehicle whether signed here or agreed to by telephone or by other electronic means. Furthermore, following the completion of my vehicle i understand that autopoint may file a mechanics lien to secure its business interest and or satisfy the repair bill.

Authorized by: _____ Date: / /

Any person who knowingly or willfully presents a false or fraudulent claim for payment of a loss or benefit or who knowingly or willfully presents false information in an application for insurance is guilty of a crime and may be subject to fines and confinement in prison.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS THAT ARE NOT MANUFACTURED BY THE ORIGINAL MANUFACTURER OF THE VEHICLE OR BY A MANUFACTURER AUTHORIZED BY THE ORIGINAL MANUFACTURER TO USE ITS NAME OR TRADEMARK. THE USE OF CERTAIN AFTERMARKET CRASH PARTS MAY MODIFY THE ORIGINAL MANUFACTURER'S WARRANTY ON THE CRASH PARTS BEING REPLACED. UPON REQUEST OF THE CUSTOMER, THE BODY SHOP SHALL PROVIDE, IF AVAILABLE, A COPY OF ANY WARRANTY FOR AN AFTERMARKET CRASH PART USED.

Customer: Buck, Carroll

Job Number:

2021 GMC Terrain SLE FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection white

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR1FJ18, CCC Data Date 12/16/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: Buck, Carroll

Job Number:

2021 GMC Terrain SLE FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection white

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
3	Empire Auto Parts 1791 Crossroads Drive Odenton MD 21113 (888) 700-8074	#G1269 RECOND Bumper cover w/o park sensors Quote: 123065928 Expires: 12/20/24	\$ 410.67
5	Keystone, Inc 4803 HOLLINS FERRY RD HALETHORPE MD 21227 (410) 636-4600	#GM1015145C A/M CAPA Lower cover black, w/o fog lamps w/o oil heater Quote: 2787797238 Expires: 02/02/25	\$ 357.00
7	Empire Auto Parts 1791 Crossroads Drive Odenton MD 21113 (888) 700-8074	#C3634 A/M Guard Quote: 123066808 Expires: 12/20/24	\$ 21.54
10	Ourisman Chevrolet of Rockville 807 Rockville Pike Rockville MD 20852	#84236083 Grille assy SL, SLE +30% Quote: 3176865904 Expires: 01/18/25	\$ 615.71
11	Yerty Auto Service & Parts 8358 Woodbury Pike Roaring Spring PA 16673 (814) 695-8079	#24498A LKQ Grille assy SL, SLE GRILLE-UPPER, SLE, W/O BLACK EDITION,4DR,*IQ* #84236083,S#24498A Quote: 3171469327 Expires: 01/18/25	\$ 275.00
14	KSI Trading Corp. 8080 AMF Drive Mechanicsville VA 23111 (800) 552-2867	#3975003 A/M License bracket Quote: 160021692 Expires: 12/26/24	\$ 23.00
18	Keystone, Inc 4803 HOLLINS FERRY RD HALETHORPE MD 21227 (410) 636-4600	#RAD13682 A/M KEYSIQ Radiator Quote: 2787844947 Expires: 02/02/25	\$ 176.47
19	KSI Trading Corp. 8080 AMF Drive Mechanicsville VA 23111 (800) 552-2867	#398871FQ A/M CAPA Shutter upper Quote: 160004722 Expires: 12/26/24	\$ 208.20
20	KSI Trading Corp. 8080 AMF Drive	#398871CQ A/M CAPA Shutter lower	\$ 106.00

Preliminary Estimate

Customer: Buck, Carroll

Job Number:

2021 GMC Terrain SLE FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection white

	Mechanicsville VA 23111 (800) 552-2867	Quote: 160004806 Expires: 12/26/24	
24	LKQ Corp 4803 Hollins Ferry Rd Halethorpe MD 21227 (410) 636-4600	#~406790761 LKQ Fan assy +30% Radiator or Condenser Fan Motor (FAN ASSEMBLY),S#\$ST274 Quote: 2787854242 Expires: 02/02/25	\$ 289.00
25	Keystone, Inc 4803 HOLLINS FERRY RD HALETHORPE MD 21227 (410) 636-4600	#CAC010187 A/M KEYSIQ Intercooler Quote: 2787858424 Expires: 02/02/25	\$ 195.45

Preliminary Estimate

Customer: Buck, Carroll

Job Number:

2021 GMC Terrain SLE FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection white

ALTERNATE PARTS USAGE

2021 GMC Terrain SLE FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection white

VIN: 3GKALMEV3ML317940 Interior Color: Mileage In: Vehicle Out:
License: Exterior Color: white Mileage Out:
State: MD Production Date: Condition: Job #:

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	7	7
Optional OEM	Automatically List	0	0
Reconditioned	Automatically List	1	1
Recycled	N/A	3	2

Preliminary Estimate

Customer: Buck, Carroll

Job Number:

2021 GMC Terrain SLE FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection white

RECALL INFO

2021 GMC Terrain SLE FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection white

VIN: 3GKALMEV3ML317940	Interior Color:	Mileage In:	Vehicle Out:
License:	Exterior Color: white	Mileage Out:	
State: MD	Production Date:	Condition:	Job #:

The National Highway Transportation and Safety Administration (NHTSA) has issued 2 safety-related recall notice(s) that may apply to the selected vehicle.

NHTSA ID: 23V339000 **Issued: May 5, 23** **Number of Vehicles: 00668187**

CHILD SEAT General Motors, LLC (GM) is recalling certain 2020-2023 Chevrolet Equinox and GMC Terrain vehicles. The four rear-seat lower child seat LATCH anchorage bars may have excessive powder coating, which could prevent a child seat from being installed with the anchorage bars. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 225, "Child Restraint Anchorage Systems." The inability to install a child seat with the LATCH anchorage bars could result in an unsecured child seat, increasing the risk of injury in a crash. Owners are advised to install child seats using the vehicle's rear seat belts until the remedy is complete. Dealers will inspect the latch anchorage bars, and remove and replace the finish, as necessary, free of charge. Owner notification letters are expected to be mailed June 26, 2023. Owners may contact Chevrolet customer service at 1-800-222-1020 or GMC customer service at 1-800-462-8782. GM's number for this recall is N232403240.

NHTSA ID: 21V612000 **Issued: Aug 8, 21** **Number of Vehicles: 00007082**

TIRES General Motors, LLC (GM) is recalling certain 2021-2022 Chevrolet Equinox and GMC Terrain vehicles equipped with certain Hankook tires. The tires may have been manufactured with an insufficient amount of curative agent, which could cause tread separation. Tread separation can result in a loss of vehicle control, increasing the risk of a crash. Dealers will inspect the tire DOT numbers, and replace any affected tires, free of charge. Owner notification letters are expected to be mailed September 20, 2021. Owners may contact GMC customer service at 1-800-462-8782; and Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N212343560.