





## Crystal




## Reset




## Vmeter




## Power Supply



## ModeSelect



## USB



Sheet: mcr-1

Peripheral

File: mcr-1.sch

Sheet: motordriver

Motor Driver

File: motordriver.sch

Sheet: /  
File: mcr.sch

**Title:**







Size: A4  
KiCad E.D.A. kicad (5.1.2)-2

Date:

Rev:

Id: 1/3

# Motor driver



Sheet: 2/3

File: motor\_driver.sch

Title:








Size: A4

Date:

KiCad E.D.A. kicad (5.1.2)-2

Rev:

Id: 2/3



Sheet: /mcr-1/		D
File: mcr-1.sch		
<b>Title:</b>		
Size: A4	Date:	
KiCad E.D.A.    kicad (5.1.2)-2	Rev: Id: 3/3	