




Programming & debug




Optocouplers




Motor Driver




Endstops




Red Green Yellow Indication




USB-C for Mini




uUSB for Raspberry to Mini




Raspberry PWR Reset




Chamber Closed Button




USB for MCU




Start Button




Motor Control Buttons




LED Display



Raspberry



MCU Reset



+5v and +3v3

