


This cable might need more connections TSI needs to decide. Suggestion, bring all pots back

Connect to TSI where packs are during Dyno room testing before the packs are ready



"Preliminary, Do not fabricate"

LAFAYETTE