

# CSV to DXF

Input, CSV

Browse...

Output, DXF


Browse...

## PREVIEW

Point Id	Easting	Northing	Height	Code
0001	567891.012	177845.123	4.345	Col
0002	567891.012	177845.134	4.346	Col
0003	567891.012	177845.123	4.345	Slab
0004	567891.012	177845.123	4.345	Slab

Separator

comma ▼

☐ 3D 

Text Height

1.0

Preview  
refreshes  
when new  
inputfile is  
chosen


When checked  
the drawing items  
will have height  
coordinates set,  
otherwise height will  
be 0.0

## What to display on drawing


- ☒ point number
- ☒ height
- ☒ coordinates
- ☐ code

Convert

## Opening screen



## Tap CONVERT



## RESULT SCREEN

