



2017

Using DynaCon Inventor Add-In Software

INSTALL AND USE GUIDE



Table of Contents

Installation	2
Copying Files	2
Usage.....	3
Part Information Form	3
Bill of Materials Form (Part).....	4
Bill of Materials Form (Assembly)	5
Routing Form	6
Hardware Insert Form.....	7
Check Imports Form.....	7
Save Formats Form	8
License.....	9

Installation

Copying Files

1. To install the Add-In Software copy the “.DLL” into the bin folder of Autodesk bin folder.
The file path should be this:
“C:\Program Files\Autodesk\Inventor 20XX\Bin”.




2. Next you will copy the “.ADDIN” file into the Autodesk Add-In Folder under Program Data. The file path should be this: “C:\Program Data\Autodesk\Inventor 20XX\Addins”.

Hint: sometimes this folder will be hidden to the user. To show this folder, make sure you are able to see these hidden folders.

3. Once these files have been copied into the right directories. You can begin to use the Add-In software.

4. To double check to make sure installation went correctly. Open Inventor and open a new part. If you have done it correctly, you will now see the “DynaCon” tab in the Ribbon options.



Usage

Part Information Form
Accessible: Assembly and Part
Ribbons.

Button:



Fields

1. Indicates Part Number.
2. Short description of part.
3. How the part will be measured.
4. Complete detail description of part.
5. Indicates finished product or raw material
6. Where it is available, not for sale etc.
7. Category of the part
8. Is it made in shop or purchased.
9. Customer the part is being made for.
10. Sales order number of part
11. Designer of part.
12. Manufacturer name (Purchased)
13. Manufacturer number (Purchased)

Buttons

- A. Help button that displays the meanings of all the options in drop down menus.
- B. Button that auto-selects some options to make it a purchased part.
- C. Button that auto-selects some options to make it a manufactured part.
- D. Saves information and uploads it to Manage 2000.
- E. Saves information locally
- F. Cancels current updates.

What It Does

This form will allot the user to create or update part information in Manage 2000. It will take some information already created in Inventor and automatically fill out this portion.

Part Information

EPICOR[®] Manage 2000[®] Import Part

Part Number CUS01085 **1**

Item Description .25" Flt Gap Fill End **2**

Unit Of Measure EA **3** ▾

Extended Description

.25" HDPE Flight gap filler. Fits on EDNX and EDNX-4b modules. Accomodates TENX end with KIT3__ flapper. **4** ▾

Inventory Type RA **5** ▾

Engr Status S **6** ▾

Sales Code **7** ▾

Lead Time Code M **8** ▾

Customer Phoenix Closure **9**

SO# 306624 **10**

Engineer nate **11**

Mfg. Name NRLSystems **12**

Mfg. Part Number nrl7777 **13**

A ? **B** Pur. **C** Man. **D** Upload **E** Save **F** Cancel

Bill of Materials Form (Part)

Accessible: Part Ribbon.

Button:



Fields

1. Indicates Part Number.
2. Material to be used by part.
3. Amount of material used in square inches.

Buttons

- A. Uploads material information to Manage 2000.
- B. Prompts the user to select the cut of the part and calculates the square inches.
- C. Cancels the transaction.

What It Does

This form will allow the user to add or update the bill of materials for a part in Manage 2000. This form will only open when the user is in a part document. Otherwise the Assembly Bill of Materials form will open.

Bill of Materials Form (Assembly)

Accessible: Assembly Ribbon.

Button:



Buttons

- A. Uploads material information to Manage 2000.
- B. Saves bill of material information.
- C. Cancels the transaction

What It Does

This form will allow the user to add or update the bill of materials for an assembly created in Inventor. It will automatically gather all the parts used in the assembly and their quantities. The user can create new parts within this form to add them to the bill of materials. But it is recommended not to do this. The check box on the right side of the table indicates whether or not to include this part in the bill. Only parts that have this selected will be included in the bill of materials.

Part Number	Quantity	Included?
NRL1234	1	<input checked="" type="checkbox"/>
NRL000	1	<input checked="" type="checkbox"/>
SCA382	5	<input checked="" type="checkbox"/>
SCA1000	1	<input checked="" type="checkbox"/>
*		<input type="checkbox"/>


A
B
C

Upload
Save
Cancel

Routing Form

Accessible: Assembly and Part Ribbons.

Button:



Fields

1. Indicates Part Number.
2. New routing sequence number.
3. Where the sequence will happen.
4. Amount of people required for assembly.
5. Amount of time needed for this part.
6. Explaining what this task is for.
7. Area where all current sequences are stored.

Buttons

- A. Quick access button that adds sequence 10, 20, and 30 for cutting, rounding and tapping.
- B. Quick access button for sequences 10 and 20.
- C. Quick access button for sequences 10, 20 and 30 for cutting, rounding and bending.
- D. Uploads all information in table 7 to Manage 2000.
- E. Adds sequence defined in fields 1-6 to table 7.
- F. Cancels the current transaction.

What It Does

This form will allow the user to add or update the routing information to Manage 2000.

Seq	WC	Crew	Hours	Desc.
10	150	1	.04	Router Table
20	150	1	.04	Router Edges
30	70	1	.1	Heat and Bend

Part Number **NRL-1234** **1**

Sequence **2**

Work Center **3**

Crew Required **4**

Labor Hours **5**

Extended Description **6**

A **B** **C**

Cut, Round, Tap Cover Cut, Round, Bend

D **E** **F**

Upload Add Cancel

Hardware Insert Form


Accessible: Assembly Ribbon.

Button:



Buttons

- A. Prompts user to select one circular edge of hardware.
- B. Prompts user to select 1 or more circular edges where the user wants this hardware inserted.
- C. Finalizes the transaction and inserts hardware.
- D. Cancels the transaction.



What It Does

This form will allow the user to select the edge of piece of hardware in the assembly. Then select each individual hole where they want this piece of hardware inserted. Once the user has selected each hole, a new instance of hardware will be created and an insert constraint will be added to it to put it in the hole.

Check Imports Form


Accessible: Assembly Ribbon.

Button:



What It Does

This form will shows the user what information has been pushed for each individual part in the assembly. If the information has been added to Manage 2000, it will show a check mark in the box. Only the parts that do not have all the information added will be shown.



Save Formats Form


Accessible: Drawing Ribbon.

Button:



What It Does

This form allows the user to select the file types to save a drawing as. Then it will ask the user where they want to save the documents and it will save this drawing as these formats in the desired folder.



License

MIT License

Copyright (c) 2017 Nathan Lindenbaum

Permission is hereby granted, free of charge, to any person obtaining a copy of this software and associated documentation files (the "Software"), to deal in the Software without restriction, including without limitation the rights to use, copy, modify, merge, publish, distribute, sublicense, and/or sell copies of the Software, and to permit persons to whom the Software is furnished to do so, subject to the following conditions:

The above copyright notice and this permission notice shall be included in all copies or substantial portions of the Software.

THE SOFTWARE IS PROVIDED "AS IS", WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO THE WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT. IN NO EVENT SHALL THE AUTHORS OR COPYRIGHT HOLDERS BE LIABLE FOR ANY CLAIM, DAMAGES OR OTHER LIABILITY, WHETHER IN AN ACTION OF CONTRACT, TORT OR OTHERWISE, ARISING FROM, OUT OF OR IN CONNECTION WITH THE SOFTWARE OR THE USE OR OTHER DEALINGS IN THE SOFTWARE.