




**MURAT IRKAN MEDIATEK 7988A ROUTER-AP 2024-05**



x: Don't care

Jumper setting	SW1	SW2	SW5	SW6
SPIM-NOR	Low	Low	Low	x
SPIM-NAND	High	Low	High	x
eMMC	Low	High	x	Low
SD	High	High	x	High



SNFI-NAND(None support , internal use)
--




SNFI-NAND datasheet 沒support, 而且現在bootstrap 要SNFI 空的才會到SD

## Boot Strapping

Pin Name	Description	Boot Sequence
{GPIO_1,GPIO_0}	Boot mode	00: SPIM-NOR (SPI2) 01: SPIM-NAND (SPI2) 10: eMMC 5.1(1.8V) 11: SNFI-SD Card
{GPIO_3}	A-Die Mode	0: 2 A-Die/1 Adie SB 1: 1 A-die DBDC
UART TX0	Second A Die Xtal mode	0 : XTAL mode 1 : Buffer mode
PWM0	40MHz/80MHz Xtal select	0 : Reserved 1 : 40MHz
SYS_WATCHDOG	CPU 1.023V/ 0.85V select	0 : 0.85V 1 : 1.023V



 <a href="http://www.banania-cd.com">http://www.banania-cd.com</a>	<b>GUANGDONG BIPAI KEJI CPA.LTD</b>			
	Design Name			
	BPI-R3-MT7986A			
	Size A3	Page Name		Rev V.1.1
		CM04_MT7986_CONSYS		
Date:	Tuesday, July 19, 2022		Sheet	4 of 17

SFP 2.5G LAN

