



+1(801) 618 - 3535
info@truckranch.com

Customer
Dyllan Sorenson
(385) 229 - 5099

Vehicle
2013 Ford F-150
VIN
1FTFW1ET7DFB85359
XL: Crew Cab Pickup
3.5L V6 4DR
Turbocharged GAS FI:
4WD: AT: Crew Cab
Pickup
148,000 Mi In / 154,052
Mi Out
Stock #: A16703
Sold Date: 08/04/2022

RO# : 61010678
Tag# : 16703

Pending Recommendation(s)

| | 1. REPAIR, LOF | bank 2 vcts | Customer Pay | \$2,914.11 |
|--|----------------|-------------|--------------|------------|
| Parts | | | \$1,762.11 | |
| Name | Quantity | Unit Price | Sale Price | |
| 9-0738SA - TIMING CHAIN KIT WOULD HIGHLY RECOMMEND DOING AN LOF WITH THIS JOB | 1 | \$397.60 | \$397.60 | |
| JV5182 - TIMING COVER GASKET SET | 1 | \$110.10 | \$110.10 | |
| VS50879R - FEL V/C GASKET | 1 | \$85.08 | \$85.08 | |
| AT4Z6M280A - SOLENOID - ENGINE VARIABLE TIM | 2 | \$82.60 | \$165.20 | |
| AT4Z6279D - BOLT | 2 | \$6.69 | \$13.38 | |
| AT4Z6256B - SPROCKET | 2 | \$206.50 | \$413.00 | |
| AT4Z6C525D - CAM | 2 | \$183.75 | \$367.50 | |
| AT4Z6M280C - SOLENOID - ENGINE VARIABLE TIM | 1 | \$66.15 | \$66.15 | |
| AT4Z6M280B - SOLENOID | 1 | \$81.55 | \$81.55 | |
| AT4Z6279E - BOLT | 2 | \$7.08 | \$14.16 | |
| MI-AF - ANTIFREEZE | 16 | \$1.32 | \$21.12 | |
| MI-M48 - M48 OIL FILTER | 1 | \$2.55 | \$2.55 | |
| MI-530 - 5W30 OIL | 6 | \$4.12 | \$24.72 | |
| Labor | | | \$1,152.00 | |
| Fee | | | \$0.00 | |

| | | | | |
|-------|--------|------------------------------------|--------------|----------|
| | 2. REC | replace the left rear leaf spring. | Customer Pay | \$847.67 |
| Parts | | | \$622.67 | |




Customer
Dyllan Sorenson
(385) 229 - 5099

Vehicle
2013 Ford F-150
VIN
1FTFW1ET7DFB85359
XL: Crew Cab Pickup
3.5L V6 4DR
Turbocharged GAS FI:
4WD: AT: Crew Cab
Pickup
148,000 Mi In / 154,052
Mi Out
Stock #: A16703
Sold Date: 08/04/2022

RO# : 61010678
Tag# : 16703

+1(801) 618 - 3535
info@truckranch.com

Pending Recommendation(s)

| | | | | |
|---|---------------------------|------------------------------------|--------------------------|------------|
|  | 2. REC | replace the left rear leaf spring. | Customer Pay | \$847.67 |
| | | | | |
| | Name | Quantity | Unit Price | Sale Price |
| | DL3Z5560D - SPRING - REAR | 1 | \$546.97 | \$546.97 |
| | 9L3Z5705C - U-BOLT | 2 | \$22.12 | \$44.24 |
| | W705518S900 - NUT | 4 | \$3.93 | \$15.72 |
| | W714297S440 - NUT | 2 | \$7.87 | \$15.74 |
| | | | | |
| | Labor | | | \$225.00 |
| | | | | |
| | Fee | | | \$0.00 |
| | | | | |
| | | | Additional Fees | \$0.00 |
| | | | Additional Discount | \$0.00 |
| | | | Tax | \$280.25 |
| | | | Recommendations Estimate | \$4,042.03 |

Services

| | | | | |
|----|------|--|---------------------|---------|
| 1. | DIAG | DIAG CHECK ENGINE LIGHT, HAS MISS FIRES AND RUNNIGN RICH CODES. LAST TIME IN HERE WE FOUND OIL IN THE TRUBO SYSTEM | Customer Pay | \$90.00 |
| | | | | |
| | | | Additional Fees | \$0.00 |
| | | | Additional Discount | \$0.00 |
| | | | Tax | \$6.70 |
| | | | Current Estimate | \$96.70 |



+1(801) 618 - 3535
info@truckranch.com

Customer
Dyllan Sorenson
(385) 229 - 5099

Vehicle
2013 Ford F-150
VIN
1FTFW1ET7DFB85359
XL: Crew Cab Pickup
3.5L V6 4DR
Turbocharged GAS FI:
4WD: AT: Crew Cab
Pickup
148,000 Mi In / 154,052
Mi Out
Stock #: A16703
Sold Date: 08/04/2022

RO# : 61010678
Tag# : 16703

| | | |
|--|--------------------------|-------------------|
| | Recommendations Estimate | \$4,042.03 |
| | Current Estimate | \$96.70 |
| | Approved Total | \$0.00 |
| | Revised Estimate | \$96.70 |

X
Customer Signature

Date