

Power

HAT spec Back-feed

HAT spec EEPROM

U1

```
SDA  2
SCL  2
```

Diagram illustrating the pin connections for the P6 header:

Header Pin	Function
1	PiTx
2	ArdRx
3	PiRx
4	ArdTx
5	GND
6	GND

Connectors

Push button

I2C Pullup resistors
(Values may need to be changed)

License: CC-BY 3.0
Copyright Mark Benson 2016

Sheet: /
File: pi-2-stepper-board-hat-spec.sch

Title: Pi 2/3 Arduino Stepper board

Size: A4	Date: 2016-04-06
----------	------------------

KiCad E.D.A.	kicad 4.0.2-stable
--------------	--------------------

Rev: 1

Id: 1/1