

No : 190809985

DATE : 2020-06-14

LOCATION : KEEMK

## INWARD EQUIPMENT INTERCHANGE

CONTAINER NO : sadf2345677

20PO

SEAL -

DEST KERN

SHIPPING LINE : UNION LOGISTICS LTD

B\L NO : 190809985

VESSEL : asdf

VOY NO: asdf

TRANSPORTER : asdf

TRUCK NO: KGH 423L

DRIVER : Zappos Founder

DELIVERY NOTE :

PARTY DELIVERING CONTAINER : asdf



### Tally Report

MINOR DENTS AND SCRATCHES SEEN

Repair Code	Description of Damage/Repair Qty	Hours	Labour Cost\$	Material Cost	Total Cost
BSRF ST/1	Straighten Bottom Side Rail Flange upto first 15 cm	0.15		96	
BSRF ST/1	Straighten Bottom Side Rail Flange upto first 15 cm	0.15		96	
BSRF ST/1	Straighten Bottom Side Rail Flange upto first 15 cm	0.15		96	
BSRF ST/1	Straighten Bottom Side Rail Flange upto first 15 cm	0.15		96	

384

Prepared by : AUGUSTINE AUGUSTINE

Repair Estimated by: AUGUSTINE AUGUSTINE

