



Cons To Design

- The rope might slip b/w the rollers
- The motor may be too weak to pull all the weight up
- All the weight force in one area may serve as a downfall
- The rollers may not be able to grip the rope

UNSURE ABOUT

- If the lubricated roller should be supplied with power or not? (Make it the third roller)
- How the gears ~~will~~ will work to move the rollers, as I have no knowledge about them.