






TITLE: Logic		REV: 0.7.1
EasyEDA	Company: Your Company	Sheet: 1/3
	Date: 2024-10-16	Drawn By: valzzu



TITLE: POwaaaaa		REV: 0.7.1
EasyEDA	Company: Your Company	Sheet: 2/3
	Date: 2024-10-17 Drawn By: valzzu	



ILI9341 cannot use display and touch on the same SPI.  
The workaround is not connecting SDO / Miso.