

QUALITY ASSURANCE SHEET

To TVC QA section

2024/08/06

From Ashitaka QA section

Contents:

Material	Code		Lot no.	Quantity	Judgement
	Ashitaka	TVC			
RG HOLDER CLIP 4	RG00X104V		240613-2=	20000	OK
	【Mold Contact Management No.TR250】Holder Clip 4 Strand Update Type Gate Burr Correction				
RG HOLDER CLIP 4	RG00X104V		240616-2	100000	OK
RG HOLDER CLIP 4	RG00X104V		240617-2	180000	OK
RG HOLDER CLIP 4	RG00X104V		240618-2	80000	OK
RG HOLDER CLIP 4	RG00X104V		240705-2	140000	OK
RG HOLDER CLIP 4	RG00X104V		240706-2	200000	OK
RG HOLDER CLIP 4	RG00X104V		240707-2	180000	OK
RG HOLDER CLIP 4	RG00X104V		240708-2	200000	OK

Confirmed by:

Data/yyyy/mm/dd): 2024/08/06

Signature: 鈴木

Confirmed by:

Data/yyyy/mm/dd): 2024/08/06

Signature: [Signature]

Quality Control Manager

QUALITY ASSURANCE SHEET

To TVC QA section

2024/08/06

From Ashitaka QA section

Contents:

Material	Code		Lot no.	Quantity	Judgement
	Ashitaka	TVC			
RG PEEL M26 SHORT	RG30M701NV		240705T	77000	OK
RG PEEL M26 LONG	RG30M703NV		240711T	12000	OK
RG PEEL M26 LONG	RG30M703NV		240712T	79000	OK
DILATOR HUB 5FR	RS00X650EV		240617T7	46000	OK
DILATOR HUB 5FR	RS00X650EV		240624T1	22000	OK
DILATOR HUB 5FR	RS00X650EV		240624T2	24000	OK
DILATOR HUB 5FR	RS00X650EV		240624T3	10000	OK
DILATOR HUB 5FR	RS00X650EV		240628T1	22000	OK

Confirmed by:

Data/yyyy/mm/dd): 2024/08/06

Signature: 鈴木

Confirmed by:

Data/yyyy/mm/dd): 2024/08/06

Signature: 

Quality Control Manager

QUALITY ASSURANCE SHEET

To TVC QA section

2024/08/06

From Ashitaka QA section

Contents:

Material	Code		Lot no.	Quantity	Judgement
	Ashitaka	TVC			
DILATOR HUB 5FR	RS00X650EV		240628T2	36000	OK
DILATOR HUB 5FR	RS00X650EV		240628T3	2000	OK
DILATOR HUB 5FR	RS00X650EV		240628T3	2000	OK
PEEL POUCH 135X310	TF25X500V		240723	14000	OK


Confirmed by:

Data/yyyy/mm/dd): 2024/08/06

Signature: 鈴木

Confirmed by:

Data/yyyy/mm/dd): 2024/08/06

Signature: 
Quality Control Manager