

WORKSHOP MANAGER

DATE: 17.03.2023

CARRIAGE WORKSHOP, AJMER

Subject: Spherolastic Rubber Bearing (Silent Block) and knuckle of CBC coupler are found failure in below 6 year.

Ref: NO: ESC/RDSO/CBC/SV Dtd. 25.10.2021

Vide letter in above subject that as per reference Letter (M/S ESCORT) ESCORT Make if the Rubber of Spherolastic Silent Blocks and knuckle of CBC are found damage or crack within 6 Year of manufacture date then they will be replaced.

Therefore, ESCORT Make Rubber of Spherolastic Silent Blocks (Annexure-B) and knuckle (Annexure-A) of CBC coupler found damage or crack below 6 years of manufacturing, kindly arrange to get them replaced. This is your information and necessary action.

ATTACHED:

1. ANNEXURE-A
2. ANNEXURE-B

RAJESH KUMAR AZAD  
SSE/22

# CARRIAGE WORKSHOP AJMER SS-II SCHEDULE IN NDT FAIL REPORT-ANNEXURE A

SR NO.	DATE	COACH NO.	CODE	RLY	HEAD NO.	MFG YEAR	KNUCKLE NO.	REMARKS
1	19.4.22	182224/C	LWSCZ1	WR	18F231	2018	ME019	FAILED
2	2.5.22	121180/C	LWACCN	WR	9699	2017	11127	FAILED
3	2.5.22	121180/C	LWACCN	WR	9654	2017	RTQ4655	FAILED
4	31.5.22	181071/C	LWACCN	WR	5557	2018	3075	FAILED
5	31.5.22	181071/C	LWACCN	WR	5689	2018	2923	FAILED
6	23.06.22	196464/C	LWLRRM	NW	9746	2019	D4	FAILED
7	23.06.22	196464/C	LWLRRM	NW	9759	2019	D6	FAILED
8	23.7.22	196255/C	LWACCW	NW	9144	2019	P4851	FAILED
9	27.7.22	196238/C	LWACCW	NW	9371	2019	11043 ,	FAILED
10	8.8.22	196120/C	LWACCW	NW	1004	2019	11817	FAILED
11	13.8.22	196894/C	LWSCN1	NW	1554	2019	M9087 .	FAILED
12	25.8.22	196467/C	LWSCN1	NW	1646	2019	NO TAG	FAILED
13	25.8.22	196467/C	LWSCN1	NW	1673	2019	NO TAG	FAILED
14	29.8.22	196921/C	LWACCN	NW	1796	2019	NO TAG	FAILED
15	31.8.22	196470/C	LWSCN-1	NW	1667	2019	NO TAG	FAILED
16	31.8.22	196470/C	LWSCN-1	NW	1671	2019	NO TAG	FAILED
17	6.9.22	11166/C	LWSCZDAC	NW	1800	2017	11333	FAILED
18	10.9.22	197865/C	LWACCN	NW	1871	2019	12917	FAILED
19	27.9.22	127207/C	LWSCN1	WR	1837	2019	12745	FAILED
20	27.9.22	127207/C	LWSCN1	NW	1852	2019	E5	FAILED
21	29.9.22	061120/C	GS	NR	4146	2018	2234	FAILED
22	21.10.22	197024/C	LWSCN	NR	4200	2019	B21	FAILED
23	17.11.22	09127/C	LWACCN	WR	8058	2017	ME978 .	FAILED
24	17.11.22	09127/C	LWACCN	WR	8043	2017	ME728 .	FAILED
25	26.11.22	196144/C	LWSCN-1	WR	1419	2019	NO TAG	FAILED
26	28.11.22	196164/C	LWSCN-1	WR	7906	2019	11587	FAILED
27	28.11.22	196164/C	LWSCN-1	WR	9707	2019	11615	FAILED
28	7.12.22	197052/C	LWSCN-1	WR	2475	2019	11329	FAILED
29	7.12.22	196154/C	LWSCN-1	WR	1020	2019	NO TAG	FAILED
30	7.12.22	196156/C	LWSCN-1	WR	1024	2019	B2	FAILED
31	14.12.22	196178/C	LWSCN-1	WR	1342	2019	12226	FAILED
32	28.12.22	196193/C	LWACCN	WR	9923	2019	NO TAG	FAILED
33	2.1.23	131050/C	LWACCN	WR	7384	2018	8418	FAILED
34	4.1.23	193917/C	LWSCN	WR	2231	2017	ME8717	FAILED
35	7.1.23	196152/C	LWSCN1	WR	1394	2019	12155	FAILED
36	7.1.23	199518/C	LWSCN1	WR	2275	2019	13	FAILED
37	18.1.23	196216/C	LWACCW	WR	1426	2019	NO TAG	FAILED
38	18.1.23	131400/C	LWACCN	WR	6656	2016	1523	FAILED
39	29.7.22	199126/C	LWACCN	NR	8003	2017	ME1760	FAILED
40	29.7.22	199126/C	LWACCN	NR	7656	2017	BRT636	FAILED
41	2.8.22	08057/C	LWACCN	NR	8372	2017	ME1839	FAILED
42	2.8.22	174066/C	LS5	WR	7917	2017	MS871	FAILED
43	2.8.22	174066/C	LS5	WR	7967	2017	5718	FAILED
44	17.3.23	202833/C	LWS	NW	3561	2020	NO TAG	FAILED

**CARRIAGE WORKSHOP AJMER SS-II SCHEDULE IN NDT FAIL REPORT-ANNEXURE B**

SR NO.	DATE	COACH NO.	CODE	RLY	HEAD NO.	MFG YEAR	REMARKS
1	29.7.22	131020/C	LWACCN	WR	7299	2018	FAILED
2	16.8.22	196894/C	LWSCN1	NW	1565	2019	FAILED
3	16.8.22	196894/C	LWSCN1	NW	1554	2019	FAILED
4	21.9.22	126135/C	LWSCZ	WR	8903	2017	FAILED
5	21.9.22	11166/C	LWSCZDAC	NW	8100	2017	FAILED
6	11.10.22	031350/C	LWACCN	WR	7307	2018	FAILED
7	11.10.22	031350/C	LWACCN	WR	7327	2018	FAILED
8	28.2.23	130640/C	LWACCW	WR	7813	2017	FAILED
9	28.2.23	16249/C	LWSCN1	WR	6581	2017	FAILED
10	3.3.23	174086/C	LS5	WR	7917	2017	FAILED
11	9.3.23	161528/C	LWLRRM	NW	9721	2017	FAILED