




Power supply isolation




4-wire resistance sense




Voltage measurement




SPI isolation



1.25 V reference



Relay control



Current measurement

