

GUGUSURE

CORDED UV LED NAIL LAMP

GEL POLISH APPLICATION

IPREPARE



To ensure proper adhesion of gel polish, it's important to prep your nails correctly. Follow these steps for optimal results:

Find the Right Workspace: Choose a clean, well-ventilated area for the gel polish application. Avoid working outdoors or in direct sunlight, as the product is light-sensitive.

Remove Existing Polish: Begin by removing any existing polish from your nails.

Wash and Dry Your Hands: Thoroughly wash and dry your hands to eliminate any oils or residues.

Push Back Cuticles: Use the slanted edge of a manicure stick to gently push back your cuticles. Ensure the cuticle area is clean and free from debris, as this can prevent the gel from adhering properly to the nail.

By following these steps, you'll create an ideal surface for the gel polish to adhere, leading to a longer-lasting manicure.



File and shape the free edge and lightly buff the shine off the natural nail with the pink side of the buffer. Do not over buff. Remove any remaining dust.



Using the Lint Free Wipe, clean nails with Gel Cleanser and allow to air dry for 15 seconds.



Apply one layer of Gel Primer sparingly to nail.



For easier removal, apply sparingly in a circle applying it to the outer edges of the nail only. Allow to air dry for 30 seconds.

LACQUER UP



Apply a thin layer of the Gel Base &Top Coat to the clean,dry nail without touching the cuticle or skin alongside the nails



Cap the free edge of the natural nail by running the polish brush along the nail tip.If necessary, use the manicure stick to clean cuticle area before curing.Please put your nails into the LED Lamp and cure for 30-60 seconds.If applying a clear manicure,skip to the "Protect"instructions.



Vigorously shake the Color Gel Polish to make the viscosity thinner and easier to apply. Apply a thin,even layer over the entire nail without touching the cuticle area.Cap the free edge of the nail by running the brush along the nail tip.If necessary,use the manicure stick to clean cuticle area before curing.Please put your nails into LED Lamp and cure for 90-120 seconds. Apply a second layer of Color Gel Polish.Place nails into LED Lamp and cure for 90-120 seconds.

TIPS &TRICKS

·We recommend applying the gel first to both thumbs and curing them together.Then,apply the gel to the other four nails on one hand and cure.Repeat the same steps on the other hand.

·For best results,apply in thin precise layers.To remove excess product from the brush,when opening the bottle,circle the inside neck of the bottle with the brush,when opening the bottle.

·DO NOT TOUCH NAILS AFTER CURING.The curing process will leave a slight moisture layer on the nails at the end of each cure,but your nails will be ready for the Color Gel Polish or the Gel Base &Top Coat application.The moisture layer will be removed with Gel Cleanser at the end of the manicure.

PROTECT



Apply a thin layer of the Gel Base &Top Coat.Make sure the gel does not touch the cuticle or skin alongside the nails.Cap the free edge of the nail by running the brush along the nail tip.If necessary,use the manicure stick to clean cuticle area before curing.Please nails into UV LED Lamp and cure for 60 - 90 seconds.



Remove the moisture layer using the Gel Cleanser and Lint-Free Wipes.

Steps for reference



00.Metal gel polish kit.



01.Shape your nails



02.Gently push back cuticles.



03.Remove extra cuticles or rough skin.



04.Buff,smooth and shine nails.



05.Clean nails.



06.Apply base coat and UV curing for 120s.



07.Apply reinforced gel.



08.UV curing for 120s



09.Wipe out the sticky.



10.Apply metallic gel twice with a thin layer ,and cure each layer UV light for 120s.



11.Apply reinforced gel again,



12.UV curing for 120s without wiping cut the sticky



13.Apply top coat and UV curing for 120s.



14.Completed Metallic Manicure Show.