



## Technical Report

**TR150567**

19-Jan.-2018

**From:**

**To:**

**Canez Power Division S.A.**  
Electrical Motor- Rewinding Section  
+509 2811 3669  
[team@canezgeneration.com](mailto:team@canezgeneration.com)

**Brasserie National D'Haiti S.A**  
Tel: +509 3701 0134  
[Adulex.blemur@heinken.com](mailto:Adulex.blemur@heinken.com)

### 1. Motor Receive.

Date In:	Jan.19 <sup>th</sup> , 2018
Description:	1 electrical motor 2.5kw
Fault:	This motor is burned.
Delivery	Jan.20 <sup>th</sup> , 2018 by Brana employee .

### 2. Repair

#### Opening process



Received



1 bearing changed



Wires burned

#### Repair Process



Stator ready



Rewinding

### 3. Final Comments

Received this electrical motor complete, then Brana got emergency for it, found wires burned:  
Job done: rewinding and 1 bearing changed.

### 4. Warranty Tag

- 15148
- 90 days warranty