



Instrumental Amplifiers

Gain for measuring nerst voltage



Gain for measuring pwm signal



Gain for measuring Ip_meas

-IN & +IN to separate side of 61.9 omega_{PWM_V1}

