



## POWER&amp;GPIO




J1 ON:  $V_{IN}=3.3V$

OFF:  $V_{IN} = 5V$






# ETHERNET



## INTERFACE &GPIO

Interface	J2	J3
PARA	OFF	ON
SPI	ON	OFF
UART	OFF	OFF



## MCU

