




## Power

Changes from Rev E:





- \* Corrected pinout problem on Ethernet RX lines
- \* Changed T2 and T3 to alternate part due to assembly issues
- \* Changed J15 to SMT testpoints instead



## MCU



## Ethernet



## Peripherals

ReFlex Hand Controller			
Title	Number	Revision	F
Size	C		
Date:	2020-05-14	Sheet of	1
File:	C:\Users\reflex.brainboard\Reflex\HandController\ReFlex_Hand_Controller_V1.0	Drawn by:	Gabrielle Merritt
Open Source Robotics Foundation			