

# EP21 ADAS HIL Report

Caoxing

December 28, 2018

## Result List

<u>0.1</u>	SAIC CCC Stright 5PctIncreace 30-90	Pass
<u>0.2</u>	SAIC CCC Stright 5PctIncreace 40-40	Fail
<u>0.3</u>	SAIC CCC Stright 5PctIncreace 120-60	LostConnection

## 0.1 SAIC CCC Stright 5PctIncrease 30-90

TestcaseName: SAIC CCC Stright 5PctIncrease 30-90  
Result: Pass  
Vehicle: EP21 2018  
Engineer: Author  
Date: 04-Dec-2018




Figure 1: TestData

## 0.2 SAIC CCC Stright 5PctIncrease 40-40

TestcaseName: SAIC CCC Stright 5PctIncrease 40-40  
Result: Fail  
Vehicle: EP21 2018  
Engineer: Author  
Date: 04-Dec-2018




Figure 2: TestData

### 0.3 SAIC CCC Stright 5PctIncrease 120-60

TestcaseName: SAIC CCC Stright 5PctIncrease 120-60  
Result: LostConnection  
Vehicle: EP21 2018  
Engineer: Author  
Date: 04-Dec-2018




Figure 3: TestData