









GOMBOK



$U_H = 3.3 \cdot 10/11 = 3V$
 $T_{charge} = 0.1ms \rightarrow 5T = 0.5ms$
 $T_{discharge} = 1ms \rightarrow 5T = 5ms$

Csatlakozó



6gomb + 1 bónusz gomb

Rögzítőfuratok



Sheet: /
 File: buttons.kicad_sch

Title: Buttons

Size: A4
 Date: 2025-11-17
 KiCad E.D.A. 9.0.5

Rev: 1.0
 Id: 1/1