




Stepper Drivers

GND
5V




GND
5V




GND
24V

XYZ Axis Steppers



A+: Yellow
A-: Brown
B+: Cyan
B-: Green

A Axis Steppers



1: Limit C
2: Limit X
3: Limit Y
4: Limit Z