



Port 4 :

- Motor A
- Motor B
- Power Supply

Port 3 :

- Encoder B
- Encoder A
- 5V
- GND

Port 1 & 2:

- Pulse Signal
- Direction Signal
- Enable
- Pend
- Fault Signal

Specification :

- 1- Output Current = 0.5 – 0.8 A
- 2- Operating Voltage = 20 – 80 VAC
- 3- Pulse Frequency = 0 -200 kHz
- 4- Minimal Pulse = 2.5 us

