


# Piezo sensors

Type 1

Lots of power




0.9mm  1.01mm




Can't handle as much  
bend

Type 2

Enough power, possibly more durable



0.15mm  1.02mm



Lots of bend and should be  
enough power, 1st choice