



Aurel

Associate II

2023-04-14 04:29 AM - edited

2023-11-20 09:26 AM

Hi everyone,

As this link is the first one when looking for "stm32 try catch", I'm adding some extra info.

The previous answer doesn't work for me.

When looking on other thread, it turns out that the problem is linked with the "-specs=nano.specs".

A solution that works for me was to choose "Standard C, Standard C++" for the runtime library:


Configuration: Debug [Active] Manage Configurations...

Tool Settings | Build Steps | Build Artifact | Binary Parsers | Error Parsers

- MCU Toolchain
 - MCU Settings
 - MCU Post build outputs
 - MCU GCC Assembler
 - General
 - Debugging
 - Preprocessor
 - Include paths
 - Miscellaneous
 - MCU GCC Compiler
 - General
 - Debugging
 - Preprocessor
 - Include paths

MCU	STM32H7A3ZITxQ	Select...
Board	NUCLEO-H7A3ZI-Q	
Floating-point unit	FPv5-D16	
Floating-point ABI	Hardware implementation (-mfloat-abi=hard)	
Instruction set	Thumb2	
Runtime library	Standard C, standard C++	
<input type="checkbox"/> Use float with pri	Standard C, standard C++	
<input type="checkbox"/> Use float with sca	Standard C, reduced C++ (--specs=standard_c_nano_cpp.specs)	
	Reduced C, standard C++ (--specs=nano_c_standard_cpp.specs)	
	Reduced C, reduced C++ (--specs=nano.specs)	

And:



And

Settings

Configuration: Debug [Active]

Manage Configurations...

Tool Settings Build Steps Build Artifact Binary Parsers Error Parsers

- MCU Toolchain
 - MCU Settings
 - MCU Post build outputs
- MCU GCC Assembler
 - General
 - Debugging
 - Preprocessor
 - Include paths
 - Miscellaneous
- MCU GCC Compiler
 - General
 - Debugging
 - Preprocessor
 - Include paths
 - Optimization
 - Warnings
 - Miscellaneous
- MCU G++ Compiler
 - General
 - Debugging
 - Preprocessor
 - Include paths
 - Optimization
 - Warnings
 - Miscellaneous
- MCU G++ Linker
 - General
 - Libraries
 - Miscellaneous

Linker Script (-T) Browse...System calls ☐ Do not use system calls from library☒ Generate map file ☐ Minimal implementation (--specs=nosys.specs)☐ Add symbol cross reference table to map file (-Wl,--xref)☒ Discard unused sections (-Wl,--gc-sections)☐ Verbose (-Wl,--verbose)☐ Do not use standard start files (-nostartfiles)☐ Do not use default libraries (-nodefaultlibs)☐ No startup or default libs (-nostdlib)



0 Kudos

Reply

Powered by

