



Revision history

1.0.0-1 (2018-08-21): original

- replace micro USB connector from SMD to THT variant,
- replace power and water pump screw terminals.

- 1.0.2-1 (2019-11-12):
 - move status LEDs.

- 1.1.0-1 (2021-05-17):
 - PCB re-design for single side component placement,
 - replace micro USB connector by another THT type,
 - replace ISP-6 programmer connector by Pogo-pin contacts,
 - replace XH2.54 connectors from SMD to THT variants,
 - replace switched-mode power supply (+5V).

- C8 removed due to auto-reset issue during programming.
- R3 value changed from 1k Ω to 330 Ω for better red LED brightness.