




Clack Reader v4  
connections  
for WS1 CI

- 1x i2c cable -TOF sensr
- 1x 3P molex -flowmeter
- 1x 4P molex –power



Groove cable  
to TOF sensor  
I2c cable

Do not use  
the free port  
on the ESP



Flowmeter  
to the back pcb  
+ delivered 3p  
cable to the  
flowmeter pcb  
from the back

4-wire  
molex  
delivered

From clorinator original cable

From  
Power  
supply