




## Pi Header



## Jumpers




Connect Pico UART to Pi UART  
for non-SWD debug chatter




SWD is always connected.

## Pico



## Indicator LEDs



Debug a Pico attached to a Pi 400  
without wires flapping in the breeze

**Luke Wren**

Sheet: /

File: pi400-pico-plate.kicad\_sch

**Title: Pi 400 Pico Plate**

Size: A5

Date: 2021-03-08

KiCad E.D.A. kicad 5.99.0-unknown-b691c18bfc117ubuntu20.04.1

Rev: B

Id: 1/1