



| Overview | | | | Site |
|-------------|-------------|-------|------------|---|
| Inspect No: | 1131 | Page: | 1/1 | AECOM - MIDLANDS HUB Drift Drive Crick Nothhamptonshire NN6 7GZ |
| Job No: | 10012 | | | |
| Customer: | AECOM | | | |
| Contact: | Rob Bewick | Date | 22/03/2023 | |
| Tel: | 7553 226429 | | | |

Pass

| Client-ID | Make / Model | Serial No | ISI Equipment No |
|-----------------|-----------------|------------|------------------|
| Entrance Lane 6 | Barrier Traffic | D224207723 | 2001378 |

Asset Photograph

| | |
|---|-------------|
| Capture photograph of Asset, including asset number | See Photo 1 |
|---|-------------|

Hazard Priority and Findings

| | |
|--|------|
| Intolerable - Defects requiring immediate action | None |
| Substantial - Defects requiring attention within a time period | None |
| Moderate - Other defects requiring attention | None |
| Tolerable - Observations | None |



General Comments

None

Engineer

Graham Willars