

EVERYTHING IN NATURAL UNITS

Zaber max travel limit: 209974

Hard limit 77000-Wafer thickness

Needle Height: 75765

Overdrive

Contact: 75765-Wafer thickness

Operating limit and MM Command: 7000-Wafer thickness

Wafer thickness:

Bottom Zaber Travel Range : 0