



WD-msg Recvd = watchdog_msg_received()
WD time-out = watchdog_timeout()
button pushed = emergency_button_pushed()

All trains have stopped.
Continue by pushing the
buttons or by starting to
move trains via the handheld
or computer