



WD-msg Recvd = watchdog_msg_received()
WD time-out = watchdog_timeout()
button pushed = emergency_button_pushed()

Timer for the computer
to gracefully stop all trains

Timer to check if the computer
managed to stop all trains.
Listen if DDC loco commands
with speed > 0 are received