



NB: – the SPI connections from the Multimoto connector boards are unused
 – the PWM/DIR connections are labelled according to the Multimoto interface

Header symbols obtained from:
<http://smisioto.no-ip.org/elettronica/kicad/kicad-en.htm>

Sheet: /
 File: due_circuit.sch

Title: Due Connector Board

Size: A4 Date: Jan. 10, 2018
 KiCad E.D.A. kicad 4.0.7

Rev: 1
 Id: 1/1