



Step-4: Attach Top Cover

Note: The parts installed in Step 3 should not be removed. They are not shown here so that the parts that need to be installed in this step can be displayed clearly.

Parts List			
Item	Qty	Part Number	Material
1	1	2-Node-Rack	----
7	1	Rack-Top-Bot-Cover	----
8	6	L-Clamp	Aluminum

Mounting Screws and Nuts	
Item	Qty
M4 x 8mm Bolt	12
M4 T-Nut	12

Dept.	Technical reference	Created by Akshay Kalia 11/21/2025	Approved by	
		Document type	Document status	
		Title 2-Node-Enclosure	DWG No.	
			Rev.	Date of issue
			Sheet 1/1	