




Work Breakdown Structure



Linear Responsibility Chart	Anahita Mahmoodi	Erik Seidelmann	Raaj Chatterjee	Dr. Amr Marzouk (Supervisor)
1.0 Understand Customer Requirements	1	1	1	3
1.1 Clarify Problem Statement	1	1	1	5
1.2 Conduct Research	2	2	1	4
1.3 Develop Objectives Tree	1	1	1	4
1.3.1 Draft Objectives Tree	1	1	1	4
1.4 Establish Project Plan	3	1	3	2
2.0 Analyze Function Requirements	1	1	1	3
3.0 Generate Alternatives	5	5	1	5
4.0 Evaluate Alternatives	1	1	1	4
4.1 Weigh Objectives	3	1	3	4
4.2 Develop Test Protocol	4	4	1	4
4.3 Conduct Tests	1	2	2	6
4.3 Report Test Results	1	2	2	5
5.0 Select Preferred Design	1	1	1	6
6.0 Document Design Results	1	1	1	5
6.1 Design Specifications	1	1	1	6
6.1.1 Hardware Specifications	1	2	2	5
6.1.2 Electrical Specifications	4	1	4	6
6.1.3 Software Specifications	1	3	1	6
6.2 Define Documentation	2	1	2	5
6.3 Draft Final Report	1	1	1	5
6.5 Final Report	2	2	2	4
7.0 Project Management	2	4	1	4
7.1 Weekly Meetings	1	1	1	4
7.2 Develop Project Plan	4	1	4	4
7.3 Track Progress	2	2	1	6
7.4 Progress Reports	1	1	1	5

KEY
1 = Primary Responsibility
2 = Support/Work
3 = Light Consultation
4 = Heavy Consultation
5 = Review
6 = Final Approval

Display Week:

18

