



A 10k potentiometer.
For blue screen:
R3=4.7k; R2=1k

fritzing