

## First Notice of Loss

2023-11-02T04:00:00Z

Claim Number: WPR23LA265

Incident Date: 2023-07-08T13:52:00Z

## Flight

Operator: nan

Purpose: INST

Airport of Record: nan

## Incident Location:

43.794444, -116.54444, Emmett, Idaho, United States

## Aircraft

Make: ROBINSON HELICOPTER

Model: R22 BETA

Category: HELI

Amateur Built: False

Number of Engines: 1

## Damage

Cause: The instructor's failure to maintain airspeed during a simulated turning autorotation, which resulted in a hard landing.

Damage: Substantial

Condition: VMC

## Injuries

Highest Injury Level: Minor

Number of Serious Injuries: 0

Number of Minor Injuries: 2



## Airplane Insurance Policy

Policy Number 10

Active: From 01/01/2024 to 31/12/2024

Policy Holder: nan

For Purpose: INST

Airport of Record: nan

### Aircraft

Make & Model: ROBINSON HELICOPTER R22 BETA

Category: HELI

### Coverage:

#### Covered aircrafts:

Airplanes

Gliders

Gyrocopters

#### Excluded:

Helicopters

#### Covered:

Pilot Mistakes or failures

Collision with animals, trees or environment

Mechanical due to engine issues, oil starvation, fuel exhaust

Student or instructor mistakes or failures

Unregistered plane or uncertified pilot

#### Excluded:

Anything else