


| | | | |
|---------------------------|-----|----|--------------------------------|
| call (Test CL) | | | |
| Modem | | | EventHelix.com/EventStudio 2.5 |
| MAC | PHY | | |
| Test Mac | phy | cl | 12-Sep-12 18:21 (Page 1) |
| "Param message exchange": | | | |
| | | | |


| Convergency Layer 4gmx v.1.0 (FAP subframe) | | | | | |
|---|----------|----|---------|-----|--------------------------------|
| Modem | | | | | EventHelix.com/EventStudio 2.5 |
| MAC | FAP CL | | | PHY | |
| test mac | cphy sap | cl | nmm sap | phy | |

12-Sep-12 18:21 (Page 2)


DL messages



DL messages



UE Configuration



The UE_CONFIG.request message did not contain all the mandatory TLVs. It should be resent with the correct information

