



T 509.925.4440
F 509.962.5807
511 N. Pine Street
PO Box 1209
Ellensburg, WA 98926
www.idealcpa.com

oil chg - 7500 miles -
VACUUM Lines - replace ALL -
pull intake manifold

1) replace 2ndary airpump
vacuum line

2) back

3) intake boots

4) CCV - cold climate version.

5) DISA VALVE (sp?)
← check sp's spring

3/16" fuel hose for
vacuum lines @

advance auto parts

Cooling #1 - \$650 = max

reset oil meter?

Balance

Eldon Bird

2003

8 VALVE 5.0HC
VTEC T

P185/70 R14

1339 cc

McPherson strut

1st hybrid w/1.31

7th civic (93hp)
gen 8 13.4hp electric

en.zofti.com

factory service manual

www.woundedwarriorproject.org

13-0009-000049775