

## Assumptions

- geom file defined


scan for surfaces and sweep them by modifying the owl file and writing a new one?

- only building static aero coeffs


load .owl geom file

forget how many knobs we have... but something like this

Image Updates next iteration → want to capture screen shot from AVL and window



after a session is ~~done~~ i would like to have a plot utility. this should be on a ~~data~~ tab, so... Also don't pay attention to this arrow



should be drop down w/ various right wing combinations of aero coeff

left wing

maybe an option for 2-D plot w/ S's added as well

