

CS: Grouped Events Dashboard

DB Query Runs Every 10 minutes. Defaults to monitored sites and "Alert" severity. All filters are linked.

Customer

*

Object Type

*

Message

*

Monitoring Status

*

Severity

Alert

Install Status

All

Remove Known Issues


No

Hide Filters

Active Event Counts by Object Type



Count of Current Events by Message



Most Recent Event

Lookups Used in Dashboard

name	num_rows
active_events.csv	2110
site_info.csv	446
_event_manager_fmc.csv	550
customer_site_info.csv	437

Events Grouped by Message and Site

site_id	customer	Install_Stat us__c	exter nal_i p	tailsc ale	eve nt_i d	message	issu e_n um	Most R ecent T imesta mp	Case Num ber	Issue _Stat us__ c	IssueCre atedDate	co unt
101	SVEN	Servi	148.5	100.	100	WC Disconnected	I-29	2023-08	23-6	Open	2023-05-	120
231		ce	9.18	80.2	46		489	-02 11:	2488		16T15:2	
			6.35	16.1				02:24			2:55.000	
				27							+0000	

site _id ↕	customer ↕	Install _Stat us__c ↕	exter nal_i p ↕	tailsc ale ↕	eve nt_i d ↕	message ↕	issu e_n um ↕	Most R ecent T imesta mp ↕	Case Num ber ↕	Issue _Stat us__c ↕	IssueCre atedDate ↕	co unt ↕
100 751	Corning Optical Communications HQ	Service	207.2 39.11 5.122	Unknown	100 46	WC Disconnected	I-30 338	2023-08-02 03:10:50	23-6 3238	Open	2023-07-10T12:20:27.000+0000	116
100 751	Corning Optical Communications HQ	Service	207.2 39.11 5.122	Unknown	130	WC COM Error.	I-30 338	2023-08-02 03:11:57	23-6 3238	Open	2023-07-10T12:20:27.000+0000	116
101 231	SVEN	Service	148.5 9.18 6.35	100.80.2 16.1 27	130	WC COM Error.	I-29 489	2023-08-02 11:03:32	23-6 2488	Open	2023-05-16T15:22:55.000+0000	114
100 392	Nobu Restaurant Chicago	Service	12.10 6.18 5.134	100.74.8 3.57	100 46	WC Disconnected	I-30 540	2023-07-29 00:15:03	23-6 3499	Open	2023-07-29T11:01:08.000+0000	46
100 392	Nobu Restaurant Chicago	Service	12.10 6.18 5.134	100.74.8 3.57	130	WC COM Error.	I-30 540	2023-07-29 00:15:40	23-6 3499	Open	2023-07-29T11:01:08.000+0000	45
100 902	Kyle2	Service	166.2 53.9 2.198	100.71.1 30.1 22	100 46	WC Disconnected	I-25 381	2023-07-29 23:31:13	22-5 7890	Open	2022-09-09T11:21:14.000+0000	10
100 902	Kyle2	Service	166.2 53.9 2.198	100.71.1 30.1 22	130	WC COM Error.	I-25 381	2023-07-29 23:31:34	22-5 7890	Open	2022-09-09T11:21:14.000+0000	10
100 758	SFO Harvey Milk T1 Boarding Area B	Service	166.1 49.6 9.138	Unknown	100 13	WC is in Error State	Unknown	2023-08-01 23:07:51				2
100 019	Ron Joyce CHC	Service	199.2 12.12 2.252	Unknown	100 13	WC is in Error State	Unknown	2023-07-30 23:24:43				1
100 019	Ron Joyce CHC	Service	199.2 12.12 2.252	Unknown	128	IGU Disconnect Error.	Unknown	2023-07-30 13:22:11				1


site _id ↕	customer ↕	Install _Stat us__c ↕	exter nal_i p ↕	tailsc ale ↕	eve nt_i d ↕	message ↕	issu e_n um ↕	Most R ecent T imesta mp ↕	Case Num ber ↕	Issue _Stat us__c ↕	IssueCre atedDate ↕	co unt ↕
100 153	Olive Bra nch Lobby	Servi ce	4.71. 28.19 6	100. 104. 52.6 3	100 46	WC Disconnected	I-28 783	2023-08 -01 13: 07:43	23-6 1539	Open	2023-03- 21T12:1 1:56.000 +0000	1
100 153	Olive Bra nch Lobby	Servi ce	4.71. 28.19 6	100. 104. 52.6 3	100 46	WC Disconnected	I-30 283	2023-08 -01 15: 01:44	23-6 1539	Open	2023-06- 30T17:3 6:46.000 +0000	1
100 308	380 N Pas toria	Servi ce	166.2 11.4 5.244	100. 79.2 15.6 5	225 25	Communication Lost wi th site for more than 2 Hours	I-30 544	2023-08 -02 08: 20:07	23-6 3506	Open	2023-07- 31T14:0 0:35.000 +0000	1
100 392	Nobu Rest aurant Ch icago	Servi ce	12.10 6.18 5.134	100. 74.8 3.57	225 25	Communication Lost wi th site for more than 2 Hours	I-30 540	2023-08 -02 10: 20:06	23-6 3499	Open	2023-07- 29T11:0 1:08.000 +0000	1
100 692	1209 Piik oi Street	Servi ce	166.2 48.20 4.34	100. 92.2 1.51	130	WC COM Error.	Unkn own	2023-08 -02 05: 57:54				1
100 714	Delaware Career Ce nter	Servi ce	66.20 3.38. 4	100. 108. 226. 48	100 46	WC Disconnected	Unkn own	2023-08 -02 10: 42:46				1
100 766	Limmatpla tz 19th	Servi ce		Unkn own	225 25	Communication Lost wi th site for more than 2 Hours	I-30 416	2023-08 -02 17: 20:05	23-6 3320	Open	2023-07- 17T13:0 8:26.000 +0000	1
100 832	1000 Inde pendence Ave SW De mo	Servi ce	166.2 53.9 3.115	100. 110. 207. 64	225 25	Communication Lost wi th site for more than 2 Hours	I-25 527	2023-08 -02 11: 20:06	22-5 8087	Open	2022-09- 17T15:1 6:49.000 +0000	1
101 154	Roosevelt HS Skylig ht	Close d	166.2 48.20 4.36	100. 126. 133. 9	225 25	Communication Lost wi th site for more than 2 Hours	I-27 028	2023-08 -02 11: 20:06	22-5 9735	Open	2022-12- 05T22:0 8:46.000 +0000	1
101 253	Lionstone Kane Nort h	Servi ce	107.2 03.4 0.121	100. 78.3 3.10 8	273 17	Sensor data is not av ailable for last 10 m in, Please check the connectivity status	I-30 335	2023-07 -26 06: 03:43	23-6 3232	Open	2023-07- 09T22:2 1:10.000 +0000	1

site _id ↕	customer ↕	Install _Stat us__c ↕	exter nal_i p ↕	tailsc ale ↕	eve nt_i d ↕	message ↕	issu e_n um ↕	Most R ecent T imesta mp ↕	Case Num ber ↕	Issue _Stat us__c ↕	IssueCre atedDate ↕	co unt ↕
101 525	Boston Un iversity CFA	Servi ce	128.1 97.5. 164	100. 73.7 1.60	225 25	Communication Lost wi th site for more than 2 Hours	I-30 004	2023-08 -02 11: 20:07	23-6 2958	Open	2023-06- 17T23:2 6:56.000 +0000	1
101 528	SL Green 185 Broad way Build ing	Servi ce	108.3 0.22 5.194	100. 87.5 3.27	225 25	Communication Lost wi th site for more than 2 Hours	I-30 537	2023-08 -02 11: 20:08	23-6 3496	Open	2023-07- 29T10:4 4:50.000 +0000	1
101 554	Catalyst Office Ca mpus Phas e I	Servi ce	166.1 49.6 9.138	100. 118. 92.3 7	128	IGU Disconnect Error.	Unkn own	2023-08 -02 08: 19:53				1
101 665	300 Ameri can	Activ e	63.4 2.16 3.17	100. 92.3 6.30	225 25	Communication Lost wi th site for more than 2 Hours	I-30 339	2023-08 -02 09: 20:09	23-6 3248	Open	2023-07- 10T19:1 5:43.000 +0000	1
101 670	Tavistock IeAD 5G I ncubator	Servi ce	166.2 48.20 0.222	100. 109. 189. 78	225 25	Communication Lost wi th site for more than 2 Hours	I-30 505	2023-08 -02 11: 20:08	23-6 3444	Open	2023-07- 25T11:0 7:52.000 +0000	1
101 807	220 Guyer Road	Activ e	69.12 6.14 9.31	100. 78.5 6.28	100 13	WC is in Error State	Unkn own	2023-08 -01 23: 21:25				1
101 819	Windmill Toronto O ffice	Close d	142.1 15.2 7.107	100. 123. 220. 24	225 25	Communication Lost wi th site for more than 2 Hours	Unkn own	2023-08 -02 11: 20:09				1
101 841	Kent Coun ty YMCA	Servi ce	166.1 44.11 5.169	100. 126. 238. 22	128	IGU Disconnect Error.	I-26 256	2023-08 -02 11: 18:46	22-5 8796	Open	2022-10- 13T17:3 0:46.000 +0000	1
140 519 44	San Leand ro Tech	Servi ce	64.20 1.25 2.36	100. 122. 237. 94	100 13	WC is in Error State	Unkn own	2023-08 -02 09: 06:06				1
140 519 44	San Leand ro Tech	Servi ce	64.20 1.25 2.36	100. 122. 237. 94	100 46	WC Disconnected	I-24 086	2023-08 -01 13: 45:46	22-5 4625	Open	2022-06- 14T18:1 6:57.000 +0000	1

Number of Events Resolved (Last 7 Days)

230,125

Count of Resolved Events by Message (Last 7 Days)



Cleared Events by site and Message (Last 7 Days)

site_id	event_id	customer	message	count
100692	10046	1209 Piikoi Street	WC Disconnected	13423
100459	10013	300 N Beretania ASB Campus	WC is in Error State	4950
101584	10013	PHX Terminal 4	WC is in Error State	4531
100751	10013	Corning Optical Communications HQ	WC is in Error State	4005
100692	130	1209 Piikoi Street	WC COM Error.	3345
100855	10016	Calgary Cancer Centre	Failed to Apply new tint	2418
100899	10013	Methodist University Hospital Additions Upgrades	WC is in Error State	2395
101872	10013	80 Bond St North	WC is in Error State	2288
101547	10013	80 Bond St South	WC is in Error State	2275
100686	10013	East Carolina University Student Union	WC is in Error State	2247
100429	10013	SLTC Phase II Building B	WC is in Error State	1901
101872	10016	80 Bond St North	Failed to Apply new tint	1526
101512	10012	Tavistock Wave Hotel	Window controller is in idle state	1367
101512	10015	Tavistock Wave Hotel	Tint execution took long time	1288
100153	10046	Olive Branch Lobby	WC Disconnected	1163
100251	10013	6280 America Center	WC is in Error State	1043
100751	10016	Corning Optical Communications HQ	Failed to Apply new tint	1038
101872	10046	80 Bond St North	WC Disconnected	1000

site_id ↕	event_id ↕	customer ↕	message ↕	count ↕
100266	10013	Reston Tower 1	WC is in Error State	857
100429	10016	SLTC Phase II Building B	Failed to Apply new tint	789
100291	10016	391 San Antonio Rd	Failed to Apply new tint	645
101248	10013	Watershed Office Building	WC is in Error State	636
100291	10013	391 San Antonio Rd	WC is in Error State	613
100751	10046	Corning Optical Communications HQ	WC Disconnected	580
100465	10013	Alief Career Center	WC is in Error State	528

« Prev **1** 2 3 4 5 6 7 8 9 10 Next »