


POCO X6 FINGERPRINT

DIGITAL BOARD ESQUEMAS DIGITALIZADOS

TOP

BOTTOM



FINGER PRINT SENSOR KAM NHI KR RHA

1 - FINGER CHANGE KRKE CHECK KRE

2 - HARDWARE SOLUTION ME DEKHKR FINGER
KI LINES CHECK KRE

UNME PHLE GR CHECK KRE (GR CHECK KRNE
KE LIYE - BATTERY NIKAL
KR METTER KO DIODE MODE PR LGAKR RED
WIRE KO GND OR BLACK SE LINE CHECK KRE)

3 - HARDWARE SOLUTION DEKHKAR VOLTAGE
CHECK KRE (VOLTAGE CHECK KE
LIYE - PHON KO CHALU KRKE METTER KO
VOLTAGE MODE KRKE BLACK WIRE KO
GND OR RED SE LINE CHECK KRE)

4 - VOLTAGES OR GR OK MILE TO SERVICE
CENTRE SE FINGERPRINT KO CALIBRATION
KRWAO