

ERABASE

ERABASE INDUSTRY SDN BHD

NO.23, JALAN ISTIMEWA 4, TAMAN PERINDUSTRIAN CEMERLANG, 81800 ULU TIRAM, JOHOR
Tel: 07-861 6039 Email: enquiry@erabase.my www.erabase.my

Corrective Maintenance Note:

Document#FRM/CM/1
REV:00
ID: CM-F314FC33

Department:	CNC Autolathe	Machine:	CINCOM B012
Reported By:	test	Contact No:	N/A
Category:	Alarm	Priority:	High
Date Time:	02/07/2025 05:26	Machine Status:	Down

Issue Description:

Abnormal sound with turret. Hydraulic motor high temperature

AI Summary:

"Abnormal sound from the turret; hydraulic motor temperature is high."

Remedies and Actions Taken:

Date Time	Task Performed	Part Changed	Machine Status	Technician
02/07/2025 05:36	Abnormal sound with turret. Hydraulic motor high t	ff	Down	erw

Cost Summary:

Total Labor Cost:	RM 0.00
Total Parts Cost:	RM 23.00
Total Cost:	RM 23.00

Authorized by: _____

Date/Time Printed: 04/07/2025 05:22